## Criteria for Updating OASIS/OSM

Present Operating Version	Action Plan
3.00.59 or below	Update immediately with 3.00.92
3.00.81	Update to 3.00.92 in closed loop signal systems to interface with Translink32 and provide fixes to system related functions; update in isolated intersections during normal preventive maintenance

Note: All 2070L controllers repaired at the Traffic Electronics Center will always be upgraded to the latest approved version.

## Modem Requirements

- Must use U. S. Robotics V.92
- U. S. Robotics V.90 can be updated through a downloadable firmware upgrade